



DSPbR-013

## **SERVICE BULLETIN DSPbR-013**

**Product: DSPbR Rebroadcast Repeater**

**Subject: Firmware 5.2.4 Release**

**Date: 27<sup>th</sup> January 2015**

### Description

This Service Bulletin announces the release of baseline 5.2.4 firmware for the DSPbR Rebroadcast Repeater (DSPbR) series products.

### Product Enhancements

The version 5.2.4 firmware addresses the following product issue;

- i) When operating in a multi-rack configuration, the Master DSPbR chassis can produce spurious alarms from the Slave chassis.

### Upgrading to Firmware 5.2.4

**Note:** Please read all Service Bulletins published from the release of the firmware currently operating in your DSPbR prior to commencing an upgrade to this version 5.2.4 firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your DSPbR.

### Cost Impact

Firmware version 5.2.4 is available to RFI customers at no charge.

- END -